



"Earthen berm" from inside the dike. Approx. 3'.



Security fence in the south-east corner of the dike.

235214







①

Unfinished dike with "earthen berm". Hackensack River in the foreground.



②

"Earthen berm" composed of broken asphalt, brick, wood and soil. Approx. 7'.